



Source: 2016 & 2019 point data provided by the City of Northampton on MassGIS 2014 orthoimagery.

MAIN STREET TREES

Northampton, MA
Map produced by Toole Design May 25, 2021

Of the 57 tree pit locations within the project area, 44 were identified as having trees in them: 28 in very good to good condition and 12 in fair condition. Fifteen (15) species are represented, with 20% (9) thornless honeylocust and 20% (9) pin oak as the most common species.

Geographic and mapping information presented [in this document is for informational purposes only, and is not suitable for legal, engineering, or surveying purposes. Mapping products presented herein are based on information collected at the time of preparation. Toole Design Group, LLC makes no warranties, expressed or implied, concerning the accuracy, completeness, or suitability of the underlying source data used in this analysis, or recommendations and conclusions derived therefrom.

0 75 150 300 Feet

TOOLE
DESIGN